



Figure 1 (to Supplement 1, FER-234). Fault rupture mapped by William Lettis and Associates (1993) is highlighted in yellow. A check mark (✓) indicates area photo checked and verified by Bryant (this report). Not all areas were photo checked.